1. (1) set of timer with four cables.


2. Install the timer near the IC board.

3. (4) terminals connected to the new timer with cables.

4. #3 close-up.