






INDUSTRIAL AIR QUALITY, INC. (IAQ)
 Main: (919) 562-7181 Fax: (919) 562-7182
 Toll Free: (800) 232-9559
 www.industrialairquality.com
 Email: info@iaqsales.com







JOB Curtis Sept 6/11
 SHEET NO. _____ OF _____
 CALCULATED BY _____ DATE _____
 CHECKED BY _____ DATE _____
 SCALE _____

Schuttles

	.078	
		
	.071	
		
	.112	
		
	.112	
		
20100663		
	.170	
ODR 3000		
○ .9	.034	
○ 1.5	4.59	
○ 1.0	25.2	
	81.5	
3 Machines Running		


+
+

MW12 Murata

		
		
		
		
		
ODR		
		
20100304		
○ 4.0	1.76	
○ 1.0	11.5	
○ .5	82	
	150	

.598 Around Machine
 Running

Murata Across for ODR 3000



6.48mg/m³ Discharge
 ESP From Schuttles
 .43 Ambient in Front of Machines