


(4) SMI OUT OF SERVICE MACHINES



COLOR LEGEND:
 BLUE = 1ST TO MOVE
 RED = 2ND TO MOVE
 BROWN = 3RD TO MOVE

BLUE ITEMS INCLUDED BUT NOT SHOWN:

- RAW STOCK
- ROTATING FORK LIFT
- TOOL GRINDER
- NEW OIL TANK
- TOOLING CABINETS
- (2) 4' SCALES
- I-BEAM AND HOIST

ITEMS INCLUDE BUT NOT SHOWN THAT WILL MOVE LAST AFTER BROWN:

- SUMP-SUCKER
- AIR COMPRESSORS
- MACHINES #2,3,6,8
- CAT. FORK TRUCK

ITEMS TO MOVE LAST OR WHEN THERE IS SPACE:

- INSPECTION BENCHES
- BOWDEN
- BAND SAW
- LATHE
- BOWDEN
- HEBCO AND BENCH

ODF 2000
 Five units
 Platform for five
 ODF 2000. There
 is room for a
 sixth ODF 2000.
 Built by others

WASH AREA
 SCREEN WASHER 220V.
 BELT WASHER 480V.
 DRYER 480V.