



**INCOMING BAR STOCK AND STORAGE**

**(4) SHE OUT OF SERVICE MACHINES**



**COLOR LEGEND:**  
 BLUE = 1ST TO MOVE  
 RED = 2ND TO MOVE  
 BROWN = 3RD TO MOVE

**BLUE ITEMS INCLUDED BUT NOT SHOWN:**

- RAW STOCK
- ROTATING FORK LIFT
- TOOL GRINDER
- NEW OIL TANK
- TOOLING CABINETS
- (2) 4' SCALES
- I-BEAM AND HOIST

**ITEMS INCLUDE BUT NOT SHOWN THAT WILL MOVE LAST AFTER BROWN:**

- SUMP-SUCKER
- AIR COMPRESSORS
- MACHINES #2,3,6,8
- CAT. FORK TRUCK

**ITEMS TO MOVE LAST OR WHEN THERE IS SPACE:**

- INSPECTION BENCHES
- BOWDEN
- BAND SAW
- LATHE
- BOWDEN
- HEBCO AND BENCH

Platform for five ODF 2000. There is room for a 6th ODF 2000. Built by others

NOTE: AIR HOISTS TO BE LOCATED 5' BACK FROM THE FRONT OF ALL MACHINES AND CENTERED.

Notes:  
 1. Bottom of to be 10" off of floor  
 2. To cut hole in floor for 4" dia. connection.  
 3. Each drop will have a factory damper for air flow adjustment

WASH AREA:  
 SCREEN WASHER 220V.  
 BELT WASHER 480V.  
 DRYER 480V.