

Notes:

A) DDF 1000C has a .85Hp Motor. Full load amps at 480 volts are 5.0 amps

B) IAQ will provide a P-Trap with ball valve and attach to unit. Do you want the drain line to run back to the machine or sump??

Industrial Air Quality
102 AG DRIVE
102 AG DRIVE
102 AG DRIVE
103 AG DRIVE
104 AG DRIVE
105 AG D

Revision Date: