


Plan View of Ductwork Layout Balance Drawing Block Line-#3-CNC Cell # 3

Machine connection:
Each connection is a 5.75" ID
Raw Raw collar. Attach a reducer
to it; 5.5"OD Raw to 8" rolled edge.



- Notes:
- A) Each drop will have a Butterfly damper for airflow adjustment.
 - B) Each drop will have a Bleed in valve to allow for balancing.
 - C) DDF 6000F has 3 - 3.5HP 460volt 3Phase motors. Full load amps are 4.6amps each.
 - D) Drain line: By Honda.