


# Plan View of Ductwork Layout - Balance Drawing

## Head #4 GA Wash & GA Mill

DDF-4000TF  
 SN: 20071338



GA WASHER  
 GA FINAL CELL

Machine Connection 150mm (6") Coller  
 Attach 5.5" DD Raw to 8" Rolled Edge  
 to 8" Butterfly Damper, The 8" Bleed Valve

Machine Connection 8 1/4" ID Collar  
 Attach 8" DD Raw to 8" Rolled Edge  
 to 8" Butterfly Damper, The 8" Bleed Valve

- Notes:
- A) Each drop will have a Butterfly damper for airflow adjustment.
  - B) Each drop will have a Bleed in valve to allow for balancing.
  - C) DDF 4000TF has SHP 460volt 3Phase motor. Full load amps are 8.33amps.
  - D) Drain line: By Honda.