


Stackpole



A-3 System  
 4615 PU 1,2+3  
 4617 PU 1,2+3  
 4613 PU 2

A6 System  
 4613 1,2+3  
 4612 1,2+3  
 ALD 9+10

A2 System  
 7+8 + 4617+4 + 4615+4

A1 System  
 6 + Cooling Tunnel #11

A4 System  
 7+8 + 4617 #4 + 4615 #4

A5 System

ALD  
 9 500  
 10 500

4617  
 1 300  
 2 300  
 3 300  
 4 300  
 5 500

4615  
 1 300  
 2 300  
 3 300  
 4 300  
 5 500


4613  
 1 300  
 2 300  
 3 300  
 4 300  
 5 500

4612  
 1 300  
 2 300  
 3 300  
 4 300  
 5 500

Temper Washers  
 4617 4615  
 6 500  
 7 2000  
 8 2300  
 Temper Washers  
 4613 4612  
 6 500  
 7 2000  
 8 2300

CFM

Stack pole



- A-3 System 4615 PD 1, 2 & 3  
4617 PD 1, 2 & 3  
4613 PD 2
- A 6 System 4613 1, 2, 3  
4612 1, 2 & 3  
ALD 9 & 10  
7 & 8 + 4617 & 4 + 4615 & 4
- A 2 System 6 & Cooling Tunnel #11
- A 1 System 6 & Cooling Tunnel #11
- A 4 System 6 & Cooling Tunnel #11
- A 5 System 7 & 8 + 4617 & 4 & 4615 & 4

System	Room/Equipment	Count	Value
ALD	4617	1	300
	4615	2	300
	4613	3	300
	4612	3	300
	ALD 9 & 10	2	300
	7 & 8 + 4617 & 4 + 4615 & 4	5	500
	6 & Cooling Tunnel #11	3	300
	6 & Cooling Tunnel #11	3	300
	7 & 8 + 4617 & 4 & 4615 & 4	5	500
	4612	1	300
Temper Washers	4617	1	500
	4615	2	500
	4613	3	1500
	4612	3	1500
	ALD 9 & 10	2	1000
	7 & 8 + 4617 & 4 + 4615 & 4	5	2500
	6 & Cooling Tunnel #11	3	1500
	6 & Cooling Tunnel #11	3	1500
	7 & 8 + 4617 & 4 & 4615 & 4	5	2500
	4612	1	500

CFM