



INDUSTRIAL AIR QUALITY, INC. (IAQ)
 Main: (919) 562-7181 Fax: (919) 562-7182
 Toll Free: (800) 232-9559
 www.industrialairquality.com
 Email: info@iaqsales.com



JOB Accuride
 SHEET NO. 1 OF 2
 CALCULATED BY _____ DATE _____
 CHECKED BY _____ DATE _____
 SCALE _____

Issues: Chips covering screen in machine
 Chips in the duct work
 Mist
 Efficiency 10

Opening to Machine
 3x7 Front
 3x4 Top
 Volume 6'x6'x6'



ODR 3000 12003512
 2006-1025
 460/3/60



INDUSTRIAL AIR QUALITY, INC. (IAQ)
 Main: (919) 562-7181 Fax: (919) 562-7182
 Toll Free: (800) 232-9559
 www.industrialairquality.com
 Email: info@iaqsales.com

JOB Accuride

SHEET NO. 2 OF 2

CALCULATED BY _____ DATE _____

CHECKED BY _____ DATE _____


SCALE _____

1. Inlarge openings in Machine
 2. Larger Drop out Box

Issues: Chips covering screen in machine
 Chips in the duct work
 Mist
 Efficiency 10

Opening to Machine
 3x7 Front
 3x4 Top
 Volume 6'x6'x6'

ODR 3000 12003512
 2006-1025
 460/3/60



10" x 36" Opening
 with Drop out
 Box