


Trough Hood


Plan View



Material: 20 Gauge Alum.

Pop Rivet all four corners and caulk

Side View



Leave bottom open

Industrial Air Quality	
102 AG DRIVE Youngsville, NC 27596	
P# 919-562-7181 F# 919-562-7182	
Project: Danaher Tool	
Drawing: Trough Hood	
Date: 2/2/09	Drawn by: RAV
Sheet No:	

IAQ