


Ductwork Layout for Dskar dust collector

Side View



Industrial Air Quality
 102 AG DRIVE
 Youngsville, NC 27596
 PH 919-562-7181 F# 919-562-7182

IAQ

Project: Snadvik
 Drawing: Duct layout Dskar
 Date: 8/13/09 Drawn by: RAV
 Sheet No: